VCP/Brownfields Section - Site Visit Report

| SITE NAME: 4-C Laundromat |
|---|
| |
| SITE LOCATION: Ogden, Utah |
| DATE OF SITE VISIT: 27 October 2022 |
| |
| PURPOSE OF SITE VISIT: <u>DERR (Lincoln Grevengoed) visited the Site to oversee well installation and sampling.</u> |
| FIELD OBSERVATIONS: The DERR arrived at the Site around 10:00 AM. No activity was ongoing at the Site. A call to the contractor revealed that the well drilling had been postponed to the next day. The |
| DERR was able to compare where the slab had been removed for drilling to the proposed well locations |
| SPLIT SAMPLES COLLECTED: No |
| IS THE WORK BEING PERFORMED IN A MANNER CONSISTENT WITH THE ACCEPTED WORKPLAN? |
| _NA |
| Photos: |



Photo # 1: Openings in the slabs for new well borings.



Photo # 2: Boring openings.



Photo # 3: The Site from the Southwest.